DOE/RL-2004-08 Revision 1 REISSUE

New Source Review Notice of Construction Application for Construction or Modification of a Stationary Source; Criteria/Toxic Air Pollutant Emissions Associated with Transition of the Plutonium Finishing Plant Complex

Prepared for the U.S. Department of Energy Assistant Secretary for Environmental Management





EDWC

Approved for Public Release; Further Dissemination Unlimited

New Source Review Notice of Construction Application for Construction or Modification of a Stationary Source; Criteria/Toxic Air Pollutant Emissions Associated with Transition of the Plutonium Finishing Plant Complex

Date Published March 2006

Prepared for the U.S. Department of Energy Assistant Secretary for Environmental Management



Release Approval Date

Approved for Public Release, Further Dissemination Unlimited

DOE/RL-2004-08 Revision 1

TRADEMARK DISCLAIMER

Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise, does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof or its contractors or subcontractors.

This report has been reproduced from the best available copy.

Printed in the United States of America

1		CONTENTS	
2 3			
4	TERM	4S	
5 6	METE	RIC CONVERSION CHART	vi
7			
8	1.0	INTRODUCTION	
9			
10	2.0	PROJECT DESCRIPTION	1
11	2.1	TRANSITION ACTIVITIES	2
12	2.2	SECURITY ENHANCEMENTS ACTIVITIES	4
13	2.3	EMISSIONS	4
14	2.3.1	291-Z-1 Stack	
15	2.3.2	296-Z-5 Stack	
16	2.3.3	296-Z-6 Stack	
17	2.3.4	296-Z-7 Stack	
18	2.4	DIFFUSE/FUGITIVE SOURCES	
19	2.5	MISCELLANEOUS EMISSION SOURCES	
20	2.6	PROCESS FLOW DIAGRAMS	6
21			
22	3.0	CONTROL EQUIPMENT DESCRIPTION	
23	3.1	CONTROL EQUIPMENT EFFICIENCIES	
24	3.2	BACT OR T-BACT	
25	3.3	PROPOSED CRITERIA/TOXIC CONTROLS	
26			
27	4.0	AIRBORNE EMISSIONS MONITORING SYSTEMS	8
28	4.1	DESCRIPTION	
29	4.2	AIR OPERATING PERMIT REQUIREMENTS	8
30			
31	5.0	EMISSIONS ESTIMATION AND AIR IMPACT ANALYSIS	
32	5.1	CRITERIA/TOXIC AIR POLLUTANTS	
33	5.2	DISPERSION MODELING METHODOLOGY	
34	5.3	AIR QUALITY MODELING RESULTS	10
35			
36	6.0	PROPOSED CONDITIONS AND RESTRICTIONS	10
37			
38	7.0	REFERENCES	10
39			
40			
41	ŧ	APPENDIX	
42			
13			
44	A.	PROPOSED APPROVAL ORDER FOR CRITERIA/TOXIC AIR POLLUTANT	
45		EMISSIONS ASSOCIATED WITH TRANSITION OF THE PLUTONIUM	
1 6		FINISHING PLANT COMPLEX	APP A-i
17			

1	FIGURES	
2		
3		
4	Figure 1. Hanford Site.	F-1
5	Figure 2. Ventilation Schematic for the 291-Z-1 Stack for the 242-Z and 234-5Z Buildings	
6	Figure 3. Ventilation Schematic for the 291-Z-1 Stack for the 236-Z Building (PRF).	F-3
7	Figure 4. Ventilation Schematic for the 296-Z-5 Stack.	F-4
8	Figure 5. Ventilation System for the 296-Z-6 Stack	F-5
9	Figure 6. Ventilation System for the 296-Z-7 Stack (2736-ZB Building).	F-6
10	•	
11		
12	TABLES	
13		
14		,
15	Table 1. Emission Unit Stack Parameters in Calendar Year 2002.	5
16	Table 2. Estimated Release of New Source Materials for PFP Complex Transition.	
17	1	

060331.1023 iv

1		TERMS
2		
3		
4	ALARA	as low as reasonably achievable
5	ARAR	applicable or relevant and appropriate requirements
6	ASIL	acceptable source impact level
7		
8	BACT	best available control technology
9		
10	CERCLA	Comprehensive Environmental Response, Compensation, and Liability Act of
11		1980
12		
13	DOE-RL	U.S. Department of Energy, Richland Operations Office
14		
15	Ecology	Washington State Department of Ecology
16	EPA	U.S. Environmental Protection Agency
17		
18	HEPA	high-efficiency particulate air
19	3100	
20	NOC	notice of construction
21	NOCA	notice of construction application
22	D.4	
23	PA	protected area
24	PFP	Plutonium Finishing Plant
25	PFP EIS	Final Environmental Impact Statement Plutonium Finishing Plant Stabilization
26	PRF	Plutonium Reclamation Facility
27	PSD	prevention of significant deterioration
28 29	RACT	reasonably available control technology
30	RAWP	removal action work plan
31	RWP	radiation work permit
32	IX VV I	radiation work perint
33	SNM	special nuclear material
34	SQER	small quantity emission rate
35	DQLIC	Similar quantity outside rate
36	TAP	toxic air pollutant
37	T-BACT	best available control technology for toxics
38		and at the same of same of the
39	WAC	Washington Administrative Code
40	WDOH	Washington State Department of Health

METRIC CONVERSION CHART

Into metric units

Out of metric units

Length Iches 10,03937 Inches Iches							
inches 25.40 millimeters 0.03937 inches inches 2.54 centimeters centimeters 0.393701 inches feet 0.3048 meters meters 3.28084 feet yards 0.9144 meters meters 1.0936 yards miles (statute) 1.60934 kilometers kilometers 0.62137 miles (yards Area square inches 6.4516 square square 0.155 square square feet 0.09290304 square meters square centimeters square enters square meters square square square 0.386102 square square square square square 0.386102 square	If you know	y To	To get	If you know	Multiply by	To get	
Inches	Length						
Teet	inches	millim	imeters	millimeters	0.03937	inches	
yards 0.9144 meters meters 1.0936 yards miles (statute) 1.60934 kilometers kilometers 0.62137 miles (statute) Area square inches 6.4516 square centimeters square centimeters square centimeters square centimeters square centimeters square meters 1.0567 square meters square meters square meters	inches	centim	imeters	centimeters	0.393701	inches	
Mass (weight)	feet	meters	ers	meters		feet	
Area square inches 6.4516 square square square centimeters square centimeters square centimeters square	yards	meters	ers	meters		yards	
square inches 6.4516 square centimeters square centimeters square centimeters square centimeters square meters 10.7639 square square square square meters 10.7639 square square square square square meters 1.19599 square square square square square 0.386102 square square square square square square 0.386102 square squ	miles (statute)	kilome	meters	kilometers	0.62137	miles (statute)	
centimeters centimeters square meters					Area		
square feet 0.09290304 square meters 1.086 square meters 1.0567 quare meters 1.1023 tons (metric) tons (metric) 1.0367 <t< td=""><td>square inches</td><td></td><td></td><td></td><td>0.155</td><td>square inches</td></t<>	square inches				0.155	square inches	
square yards 0.8361274 square meters square meters 1.19599 square square kilometers square miles 2.59 square kilometers 3,412 square square kilometers 0.386102 square square kilometers square miles 2.59 square kilometers 3,412 square square kilometers 0.386102 square square kilometers square miles 2.204623 square square kilometers 2.47104 acres Mass (weight) Mass (weight) 0.035274 ounces pounds 0.45359237 kilograms kilograms 2.204623 pounds tons (short) 0.9071847 tons (metric) 1.1023 tons (slowed) Volume Volume Volume Volume (U.S., 1 ounces 29.57353 milliliters milliliters 0.033814 ounces (U.S., 1 (U.S., liquid) 0.9463529 liters liters 1.0567 quarts (U.S., 1 (U.S., liquid) 3.7854 liters liters 1.308 cubic feet oubic meters cubic meters <td< td=""><td>square feet</td><td></td><td></td><td></td><td>10.7639</td><td>square feet</td></td<>	square feet				10.7639	square feet	
Rilometers Ril		 			1.19599	square yards	
acres 0.404687 hectares 2.47104 acres Mass (weight) Mass (weight) ounces (avoir) 28.34952 grams 0.035274 ounces pounds 0.45359237 kilograms kilograms 2.204623 pounds tons (metric) tons (metric) 1.1023 tons (sl Volume Ounces (U.S., liquid) milliliters 0.033814 ounces (U.S., liquid) liters 1.0567 quarts (U.S., liquid) liters 0.26417 gallons (U.S., liquid) Cubic meters cubic meters 0.26417 cubic feet cubic meters cubic meters 1.308 cubic feet cubic meters Celsius <td>square miles</td> <td></td> <td></td> <td></td> <td>0.386102</td> <td>square miles</td>	square miles				0.386102	square miles	
Mass (weight) ounces (avoir) 28.34952 grams grams 0.035274 ounces pounds 0.45359237 kilograms kilograms 2.204623 pounds tons (short) 0.9071847 tons (metric) 1.1023 tons (sl Volume ounces 29.57353 milliliters 0.033814 ounces (U.S., liquid) milliliters 0.033814 ounces (U.S., liquid) liters 1.0567 quarts (U.S., liquid) liters 0.26417 gallons (U.S., liquid) cubic meters cubic meters 35.3147 cubic feet cubic feet 0.02831685 cubic meters cubic meters 1.308 cubic year Temperature Fahrenheit subtract 32 Celsius Celsius multiply by Fahren hen multiply by 5/9ths then add 32 kilowat Energy kilowat mit British t	acres				2 47104	acres	
ounces (avoir) 28.34952 grams grams 0.035274 ounces pounds 0.45359237 kilograms kilograms 2.204623 pounds tons (short) 0.9071847 tons (metric) 1.1023 tons (sl Volume ounces 29.57353 milliliters 0.033814 ounces (U.S., liquid) 0.9463529 liters liters 1.0567 quarts (U.S., liquid) 3.7854 liters liters 0.26417 gallons (U.S., liquid) 0.7645549 cubic meters cubic meters 35.3147 cubic for cubic yards cubic feet 0.02831685 cubic meters cubic meters 1.308 cubic yards Temperature Fahrenheit subtract 32 Celsius Celsius multiply by 9/5ths, then add 32 Energy kilowatt hour 3,412 British thermal unit British thermal unit 0.000293 kilowat			arcs	nectares	l	40103	
Dounds			ns	grams		ounces (avoir)	
tons (short) 0.9071847 tons (metric) tons (metric) 1.1023 tons (slower volume (U.S., liquid) quarts (U.S., liquid) volume						pounds (avoir)	
Volume Volume ounces (U.S., liquid) 29.57353 milliliters 0.033814 ounces (U.S., I quid) (U.S.	~. ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ 	 	 			tons (short)	
ounces (U.S., liquid) 29.57353 milliliters 0.033814 ounces (U.S., I quarts (U.S., Iiquid) 0.9463529 liters 1.0567 quarts (U.S., I quarts (U.S., Iiquid) gallons (U.S., Iiquid) 3.7854 liters liters 0.26417 gallons (U.S., I quarts (U.S., Iiquid) cubic feet cubic feet cubic yards 0.02831685 cubic meters cubic meters 35.3147 cubic feet cubic yards cubic meters 1.308 cubic feet cubic yards Temperature Fahrenheit subtract 32 then multiply by 5/9ths Celsius Celsius multiply by 9/5ths, then add 32 Fahrenheit Energy kilowatt hour 3,412 British thermal unit British thermal unit 0.000293 kilowat	(03.00.0)		(======)				
quarts (U.S., liquid) 0.9463529 liters liters 1.0567 quarts (U.S., I gallons (U.S., I quid) cubic feet 0.02831685 cubic meters cubic meters 35.3147 cubic feet cubic meters cubic yards 0.7645549 cubic meters cubic meters 1.308 cubic yerds Temperature Fahrenheit Subtract 32 then multiply by 5/9ths, then add 32 Energy kilowatt hour 3,412 British thermal unit British thermal unit 0.000293 kilowat			iliters	milliliters		ounces (U.S., liquid)	
gallons (U.S., liquid) cubic feet 0.02831685 cubic meters cubic yards Temperature Fahrenheit subtract 32 then multiply by 5/9ths Energy kilowatt hour 3.7854 liters liters 0.26417 gallons (U.S., 1 cubic meters cubic meters cubic meters 1.308 cubic yards Temperature Temperature Celsius Celsius Celsius British thermal unit British thermal unit 0.000293 kilowatt	quarts	liters	rs	liters	1.0567		
cubic feet 0.02831685 cubic meters cubic meters 35.3147 cubic feet cubic yards 0.7645549 cubic meters cubic meters 1.308 cubic yards Temperature Fahrenheit Subtract 32 then multiply by then multiply by 5/9ths, then add 32 Energy Energy kilowatt hour 3,412 British thermal unit British thermal unit 0.000293 kilowat	gallons	liters	'S	liters	0.26417	gallons (U.S., liquid)	
cubic yards 0.7645549 cubic meters cubic meters 1.308 cubic yards Temperature Fahrenheit subtract 32 then multiply by then multiply by 5/9ths Celsius multiply by 9/5ths, then add 32 Fahren add 32 Energy Energy kilowatt hour 3,412 British thermal unit British thermal unit 0.000293 kilowat		35 cubic 1	ic meters	cubic meters	35.3147	cubic feet	
Fahrenheit subtract 32 Celsius Celsius multiply by then multiply by 5/9ths Energy Energy kilowatt hour 3,412 British thermal unit Energy Temperature multiply by 9/5ths, then add 32 Energy Energy Energy Kilowatt hour 0.000293 kilowatt hour multiply by 5/9ths British thermal unit Energy Energy Kilowatt hour Market						cubic yards	
Fahrenheit subtract 32 then multiply by 5/9ths Energy kilowatt hour 3,412 British thermal unit Reference Subtract 32 then multiply by 5/9ths Reference Subtract 32 then multiply by 9/5ths, then add 32 Reference Subtract 32 then multiply by 9/5ths 32 then multiply by 9/5ths, then add 32 Reference Subtract 32 then multiply by 9/5ths, then add 32 Reference Subtract 32 then multiply by 9/5ths, then add 32 Reference Subtract 32 then multiply by 9/5ths, the							
Energy Energy kilowatt hour 3,412 British thermal unit British thermal unit 0.000293 kilowatunit	Fahrenheit		sius	Celsius	9/5ths, then	Fahrenheit	
kilowatt hour 3,412 British thermal British thermal 0.000293 kilowat unit				Energy			
	kilowatt hour	1 .	ll l		3237	kilowatt hour	
unit per second unit per second	kilowatt	British	ish thermal	British thermal	1.055	kilowatt	
	Force/Pressure				Force/Pressure	· , , , , , , , , , , , , , , , , , , ,	
pounds (force) 6.894757 kilopascals kilopascals 0.14504 pounds	pounds (force)		pascals	kilopascals		pounds per square inch	

06/2001

Source: Engineering Unit Conversions, M. R. Lindeburg, PE., Third Ed., 1993, Professional Publications, Inc., Belmont, California.

1 2	NEW SOURCE REVIEW NOTICE OF CONSTRUCTION APPLICATION FOR CONSTRUCTION OR MODIFICATION OF A STATIONARY SOURCE;
3	CRITERIA/TOXIC AIR POLLUTANT EMISSIONS ASSOCIATED WITH
4	TRANSITION OF THE PLUTONIUM FINISHING PLANT COMPLEX
5	
6	
7	1.0 INTRODUCTION
8	The U.S. Department of Energy, Richland Operations Office (DOE-RL) is continuing to transition the
9	existing Plutonium Finishing Plant (PFP) Complex to a state of low-risk, low-cost, long-term surveillance
.0	and maintenance pending final disposition. The purpose of this transition is to mitigate radiological and
1	chemical hazards associated with structures (and any remaining processing equipment and ancillary
2	hardware) in the PFP Complex such that the main plutonium processing structures at the PFP Complex
.3	would be ready for final disposition to be determined under the Comprehensive Environmental Response,
4	Compensation, and Liability Act (CERCLA) of 1980.
5	TELL 1 CONTROL TO THE STATE OF
6	This document is a revision to an earlier Notice of Construction (NOC) Application (DOE/RL-2004-08,
7	Revision 0, New Source Review Notice of Construction Application for Construction or Modification of a Stationary Source; Criteria/Toxic Air Pollutant Emissions Associated with Deactivation of the Plutonium
l8 l9	Finishing Plant Complex). The Washington State Department of Ecology (Ecology) issued an approval
19 20	order (DE04NWP-001, Ecology 2004) based on the aforementioned NOC application (NOCA).
21	order (DE0411 W.F-001, Ecology 2004) based on the aforementioned NOC application (NOCA).
22	Applicable CERCLA documentation, including an Ecology-approved removal action work plan
23	identifying specific radioactive air emissions monitoring requirements identified through the applicable or
24	relevant and appropriate requirements (ARARs) identification process, has been approved
25	(DOE/RL-2005-13, Rev. 0, Action Memorandum for the Plutonium Finishing Plant Above-Grade
26	Structures Non-Time Critical Removal Action, approved May 2005). Implementation of CERCLA
27	actions has been initiated; activity-specific removal action work plans (RAWPs) have been prepared (e.g.,
28	DOE/RL-2005-14, Rev. 0, Removal Action Work Plan for the Plutonium Finishing Plant Above-Grade
29	Structures: Facility Deactivation, approved May 2005). Diffuse and fugitive emissions associated with
30	the activities identified in approved work plans are not part of this NOCA. However, as appropriate, any
31	portions of this NOCA necessary to support process operations outside of the CERCLA scope will remain
32	in effect concurrent with the aforementioned CERCLA documentation.
33	
34	This NOCA also identifies activities supporting security enhancements at the PFP. The security
35	enhancements activities will be conducted concurrently with ongoing deactivation activities identified for
36	the PFP Complex.
37	
88	Therefore, a revised approval is being requested to address PFP transition. This revised NOCA
39	recognizes CERCLA documentation/authorization for a portion of the previously approved work scope,
10	as well as a transition mission in support of security enhancements.
11	
12	A A DE O TI OTE DEI CONTENTI ONI
13	2.0 PROJECT DESCRIPTION
14	The existing PFP Complex in the 200 West Area of the Hanford Site (Figure 1) historically was used to
15 16	conduct plutonium processing, storage, and support operations for national defense.
17 18	The proposed activities involve transitioning the PFP Complex to a state of low-risk, low-cost, long-term surveillance and maintenance pending final disposition. Transition was initiated as a deactivation effort,

approved in Ecology 2004. Transition includes: (1) the previous scope of deactivation [as approved by 1 Ecology (Ecology 2004)]; and (2) security enhancements activities described herein. The scope of this 2 NOCA does not include actions and activities conducted under approved CERCLA documentation [i.e., 3 4 the aforementioned action memorandum (DOE/RL-2005-13) and RAWP (e.g., DOE/RL-2005-14)]. 5 6 7 TRANSITION ACTIVITIES 2.1 8 All work would be performed in accordance with the approved radiological control procedures and as low as reasonably achievable (ALARA) program requirements as implemented by the project radiological 9 control manual, as amended. These requirements would be carried out through the activity work 10 packages and associated radiation work permits (RWP). 11 12 13 The non-radiological constituents that may be present in material generated through holdup removal and 14 deactivation and facility cleanout activities has been grouped into the following five categories. 15 (1) Impurities that are typically present in plutonium product nitrate, oxide, and metal 16 17 18 (2) Impurities that could be present from the process and laboratory chemicals. This includes laboratory 19 standards and sources. 20 21 (3) Constituents that could result from typical glovebox operations for plutonium that escapes the process 22 equipment, pipes, tanks, storage cans, etc. 23 24 (4) Constituents that could be present as a result of facility cleanout activities involving paint removal, 25 concrete scraping, glovebox and equipment removal, interior wall demolition, etc. 26 27 (5) Constituents that could be present due to general industrial transition activities, including excavation 28

and demolition of ancillary buildings.

Deactivation of the PFP Complex was addressed (DOE/RL-2004-08, Revision 0). Specific actions included the following:

Draining and/or de-energizing systems as appropriate

29 30

31

32 33

34 35

36 37

38 39 40

41

45

46

47

48 49

50

Stabilizing contaminated areas (e.g., with fixatives, sealants, paint)

Stabilizing or removing gloveboxes, process equipment, tanks, piping, fume hoods, ventilation systems, and support equipment

Removing fencing and paved parking areas adjacent to facilities

42 Installing alternate environmental monitoring, surveillance, and safety components (e.g., lighting, 43 fencing) if required 44

Removing/packaging radioactive and hazardous materials and waste, including stabilization and/or removal of asbestos, and removal, cleanup, and disposition of polychlorinated biphenyls and other regulated materials and transportation to waste management facilities

Removing equipment and system components

1 Size-reducing process equipment for disposal as waste 2

Packaging/repackaging and storing waste containers in air spaces not being ventilated through approved emission units or outside pending transport to approved locations/facilities pending final disposition

Performing physical or chemical treatment processes (e.g., neutralization, solidification, blending, 8 filtering) to render a material less hazardous or to reduce the volume

9 10 Excessing surplus equipment

11 12 Removing excess combustible material

13 14 Disconnecting utilities, piping, and network service systems (if the systems are not necessary to maintain required environmental monitoring or building safety systems), including associated 15 excavation. Note that potential excavation would be minimal and limited to the immediate vicinity of 16 17 utilities and piping 18

Ensuring adequate freeze and heat protection

Stabilizing, consolidating, or removing outside contaminated areas within the PFP Complex

Sealing cracks, gratings, and openings to the building exterior, and repairing roofs

Removing or reducing radioactive or hazardous contamination from facilities and equipment by washing, heating, chemical or electrochemical action, mechanical cleaning, or other techniques

Removing residual plutonium holdup material, which might remain throughout the PFP Complex after stabilization activities described in the Final Environmental Impact Statement Plutonium Finishing Plant Stabilization (DOE/EIS-0244-F) (PFP EIS) have been completed; packaging residual plutonium holdup meeting waste acceptance criteria for shipment to an onsite waste management facility, or thermally stabilizing material in muffle furnace operations and packaging for storage in existing PFP Complex vaults

Designing and executing modifications to operating systems and/or structures necessary to place a facility in surveillance and maintenance, pending demolition

Conducting final process operations to stabilize or eliminate residual operational materials or effluents, such as final process runs; cleaning vessels, pits and trenches; operation of small evaporators; flushing piping systems; and removal or replacement of filters

Demolishing non-process ancillary buildings

Installing alternate, temporary power sources (e.g., diesel generators)

Size-reducing and/or repackaging of fuel.

3 060331.1023

40 41

39

3

4 5

6 7

19

20

21 22 23

24

25 26

27 28

29 30

31

32 33

34 35

36 37 38

43

42

44

45 46

> 47 48

2.2 SECURITY ENHANCEMENTS ACTIVITIES

The scope of this NOCA also includes those activities necessary to support enhanced special nuclear material (SNM) storage at the PFP Complex, while continuing to be protective of personnel, the public, and the environment during ongoing deactivation. Security enhancements activities would include those actions foreseeably necessary for implementation of the proposed action, such as associated transportation activities, waste removal and disposal, and award of grants and contracts.

7 8

1

Specific actions associated with security enhancements activities could include the following work involving the potential for radioactive contamination:

9 10 11

12

13

14

15

• Excavations, inside and outside the PFP protected area (PA) to support installation of utilities and security-related devices and structures (e.g., barricades, patrol offices) and relocation of displaced activities. Security enhancements activities will require some excavation in areas of potential belowgrade contamination. In addition to excavations for building and structure foundations, it is estimated that approximately 5,000 linear feet of belowgrade ducting will installed, a portion of the water line will require replacement, connections to sewer and water lines will be required.

16 17 18

• Modifications to existing structures (e.g., moving walls, doors, railing, security monitoring equipment, electrical equipment upgrades) and/or construction of new buildings.

19 20 21

 Continued operations at 2736-Z/ZB Buildings for 3013-container packaging systems monitoring and maintenance.

22 23 24

There would be no modifications to the existing abatement equipment associated with registered stacks.

25 26 27

2.3 EMISSIONS

28 Location/physical dimensions, flowrate/temperature, and gas composition of all emissions.

29

- The non-radiological constituents that may be present in material generated through holdup removal and deactivation and facility cleanout activities have been grouped into five categories, as previously noted:

 (1) impurities that are typically present in plutonium product nitrate, oxide, and metal, (2) impurities that could be present from the process chemicals, (3) constituents that could result from typical glovebox operations during plutonium production that escaped the process equipment, pipes, tanks, storage cans, etc., (4) constituents that could be present as a result of facility cleanout activities involving paint removal, concrete scarfing, glovebox and equipment removal, interior wall demolition, etc., and
- 37 (5) constituents that could be present due to general industrial transition activities, including excavation 38 and demolition of ancillary buildings. It is noted that most of the toxic air pollutants (TAPs) that will be 39 potentially emitted as a result of the PFP Complex transition, and/or security enhancements activities,

40 have been previously emitted from PFP.

41 42

These aforementioned chemicals were addressed in previous documentation (Rasmussen 2000) and are provided as an illustration of materials present as a result of historical processing activities. A more detailed discussion of potential emissions associated with transition activities is provided in Section 7.0.

44 45

43

The following emission units represent all PFP non-CERCLA stationary sources¹. Details regarding stack height, flow rate, and operating temperature are shown in Table 1.

060331.1023 4

¹ Emission points at PFP that have transitioned to CERCLA, and not included in the scope of this NOCA are the 296-Z-3, -14, and -15 Stacks.

1

Table 1. Emission Unit Stack Parameters in Calendar Year 2002^a.

Emission unit	Stack height [feet (meters)]	Average operating flow rate [cubic feet per minute
291-Z-1	200 (61)	(cubic meters per second)] 290,000 (136)
296-Z-5	28 (8.5)	4,156 (2.0)
296-Z-6	15 (4.5)	6,684 (3.1)
296-Z-7	28 (8.5)	4,156 (2.0)

^a From DOE/RL-2004-08, Revision 0.

2 3 4

2.3.1 291-Z-1 Stack

The 291-Z-1 Stack releases filtered emissions from the 234-5Z, 236-Z [Plutonium Reclamation Facility (PRF)], and 242-Z Buildings (DOE/RL-2004-08, Revision 0).

8 9

2.3.2 296-Z-5 Stack

The 296-Z-5 Stack exhausts filtered air from the 2736-ZB Building, used for shipping and receiving operations (DOE/RL-2004-08, Revision 0).

12 13 14

2.3.3 296-Z-6 Stack

The 296-Z-6 Stack exhausts filtered air from the 2736-Z Building used for storage (DOE/RL-2004-08, Revision 0).

17 18

19 2.3.4 296-Z-7 Stack

The 296-Z-7 Stack exhausts filtered air from the 2736-ZB Building used for stabilization and packaging of plutonium-bearing materials (DOE/RL-2004-08, Revision 0).

25

26

27

20

2.4 DIFFUSE/FUGITIVE SOURCES

Unfiltered releases could occur from various activities addressed in Section 3.0. Specifically, these diffuse and fugitive emissions could result from minor amounts of excavation, packaging/repackaging and storage of waste containers, and ancillary building demolition.

28 29 30

2.5 MISCELLANEOUS EMISSION SOURCES

It is anticipated that a variety of miscellaneous small portable/temporary emission sources may be required to support PFP transition and security enhancements activities. Such sources could include commercially-available generators, pumps and/or compressors to supply power and/or other support functions for transition and security enhancements. It is expected that none of these units would exceed 500 horsepower.

36

060331.1023 5

03/2006 1 Due to uncertainties regarding specific type, size and usage of the aforementioned equipment, diesel fuel 2 consumption previously was set (Ecology 2004) at a voluntary limit of 50,000 gallons per year. The 3 resulting estimated emissions [based on U.S. Environmental Protection Agency (EPA) standard factors, in 4 tons per year are: NO_x (1); CO (0.2); SO_x (0.07); PM (0.07); CO₂ (37); aldehydes (0.02); and total 5 organic carbon (0.08). These emissions are in addition to those estimated for transition (refer to 6 Section 5.0, Table 2). Diesel fuel consumption was identified as a limitation in the previous approval 7 order (Ecology 2004) and will continue to be tracked to verify that criteria emissions remain below the 8 threshold levels stated herein. 9 10 11 PROCESS FLOW DIAGRAMS 2.6 12 Process flow diagrams of each emission unit. 13 14 Figures 2, 3, 4, 5, and 6 show the existing ventilation systems for 291-Z-1 (Figures 2 and 3), 296-Z-5, 296-Z-6, and 296-Z-7, respectively, described in Section 4.2. These emission units' process flow 15 diagrams are provided for perspective to explain controls in place for the historical processing of 16

18 19 20

17

3.0 CONTROL EQUIPMENT DESCRIPTION

plutonium-bearing materials. These controls will remain in place pending final facility disposition.

Control equipment description and reference to flow diagrams.

21 22 23

24 25

26

27

The radioactive particulate emissions from the emission units previously identified in Table 1 are controlled by testable stages of high-efficiency particulate air (HEPA) filters (refer to Section 4.3. Figures 2, 3, 4, 5, and 6). The radioactive air emissions are regulated under Washington Administrative Code (WAC) 246-247. Washington State Department of Health (WDOH)-approved activities associated with ongoing activities at the PFP Complex have multiple active radioactive air emissions NOCs, as incorporated in the Hanford Site Air Operating Permit.

28 29 30

31

32

33

Transition activities will use these existing controls, resulting in low levels of emissions of criteria pollutants and/or TAPs. These emissions, summarized in Section 5.0, are well below small quantity emission rates (SQER) described in WAC 173-460-080. Therefore, no additional controls are proposed for this process.

34 35 36

3.1 CONTROL EQUIPMENT EFFICIENCIES

Control equipment efficiencies and operational requirements.

37 38 39

40

41 42

Ventilation systems, for the structures that exhaust through registered stacks with HEPA filtration, would be operational during transition activities as practicable. An exception includes shutting down a ventilation system for a short period of time to allow fogging operations, sampling, or routine maintenance. HEPA filtration has a minimum efficiency of 99.95 percent for particles with a median diameter of 0.7 micron.

43 44 45

46

Appropriate controls such as water, fixatives, covers, containment tents, or windscreens would be applied, as needed. Soil removed during excavation activities would be covered until replaced into the excavation or otherwise dispositioned.

6

47 48

The transition operations would be performed in accordance with the controls specified in PFP work 2 documents (RWP, work package, etc.) to satisfy the principles of ALARA and requirements of industrial 3 hygiene and safety. For example, as appropriate before starting deactivation activities (such as isolating 4 utilities and piping or dismantling the exhaust system), removable contamination in the affected area(s) 5 could be reduced to ALARA. Measures such as decontamination solutions, expandable foam, fixatives, or glovebags also could be used to help reduce the spread of contamination. The aforementioned work 6 documents would be available for inspection upon request.

8 9 10

7

1

3.2 BACT OR T-BACT

Demonstrate compliance with BACT or T-BACT, as applicable [top-down assessment required for significant emissions such as those greater than SQER]

12 13 14

15

16 17

18

19

20

11

Criteria and toxic air pollutant emissions are estimated (refer to Table 2, Section 5) to be low for activities associated with the transition of the PFP Complex. Criteria emissions do not meet the definition of significant, thus do not trigger prevention of significant deterioration (PSD) review. In fact, the criteria air emissions expected are below the threshold values for exemption, as specified under WAC 173-400-110(5). Therefore, best available control technology (BACT) is satisfied by maintaining annual levels under the exempt threshold. If, in the future, the project scope changes and meets the definition of a modification that increase a criteria pollutant above the threshold level, then an abbreviated BACT assessment will be required for that constituent as supporting documentation for the NOCA.

21 22 23

24 25

26

27 28

29 30

31

The majority of toxic air pollutant emissions are anticipated to be in particulate form. Therefore, best available control technology for toxics (T-BACT) for those mixed (i.e., radioactive with non-radioactive particulates) will continue to utilize the abatement controls identified in Section 5.0 (e.g., HEPA filtration), which are required controls for NOC coverage and regulation by the WDOH. Additional process controls will be employed for particulate control (e.g., decontamination solutions, expandable foam, fixatives, glovebags, air movers for containment tents). These process controls for the remaining emissions (i.e., below acceptable source impact levels (ASILs) and/or SQERs) are proposed to satisfy best available control technology for toxics (T-BACT), as well as reasonable precautions in complying with the reasonably available control technology (RACT) for general sources emitting any fugitive dust emissions.

32 33 34

In conclusion, no additional controls are proposed/warranted in satisfying BACT, T-BACT, and/or RACT for the described activities.

39

40

41 42

43 44

PROPOSED CRITERIA/TOXIC CONTROLS

Many of the emission controls used during the transition/security enhacements activities are administrative, based on RACT principles and include ALARA techniques. It is proposed that controls in place to address radioactive air emissions satisfy RACT for transition activities that will exit a stack (refer to Section 2.3.8) in the PFP Complex. Further, as a result of the following discussion in Section 5.0, it is proposed that the existing required controls at the PFP Complex are adequate to satisfy the requirements for criteria and/or TAPs emissions. Therefore, no additional emission unit-based controls are proposed for this process.

7

45 46 47

4.0 AIRBORNE EMISSIONS MONITORING SYSTEMS

1

44

2 3 4	The following sections address airborne emissions monitoring systems.	
5	4.1 DESCRIPTION	
6 7	Provide description and capability of monitor/sampling systems, if required.	
8 9	• There is no existing monitoring for criteria pollutants or TAPs at the PFP Complex.	
10 11 12	• The projected emission levels of any pollutants regulated by WAC 173-400 or -460 from the transition of the PFP Complex are so low that the levels are not practical to measure.	
13 14	• A monitoring system for TAPs at such a low emission rate economically is not feasible.	
15 16	As a result, no additional monitoring systems are proposed for this process.	
17 18	4.2 AIR OPERATING PERMIT REQUIREMENTS	
19	Propose method to satisfy AOP periodic monitoring requirements.	
20 21 22 23 24 25 26 27	Emissions from the transition activities (refer to Sections 2.1 and 2.2) are estimated to be below the thresholds identified in WAC 173-400-110(5)(d) and the TAPs emissions are well below the SQER described in WAC 173-460-080. Thus since the scope of the activity is to deactivate the PFP Complex (i.e., ceasing operations), it is proposed that no AOP periodic monitoring is required for this transition the PFP Complex.	
28	5.0 EMISSIONS ESTIMATION AND AIR IMPACT ANALYSIS	
29 30 31 32 33 34	Emissions estimates were developed for PFP Complex transition activities based on residual levels of process materials resulting in contamination remaining from historic plutonium recovery/stabilization operations and decontamination solutions projected to be used for transition. Impacts are based on the summation of total emissions from point sources and diffuse/fugitive.	
35	5.1 CRITERIA/TOXIC AIR POLLUTANTS	
36 37 38 39	Estimate of all potential and actual emissions for criteria/toxic air pollutants [based on hours of operation per year, rate of operation, emission factors, control efficiencies, and a comparison of basel to proposed emissions (modifications only)]	in
40 41 42 43	Table 2 provides an estimation of releases of total new source material for PFP Complex transition activities (additional potential emissions due to miscellaneous sources are discussed in Section 2.3). Table 2 was developed from information associated with deactivation of a similar facility (Hebdon 200).)2)

Table 2.	Estimated Release of New Sou	rce Materials	for PFP Cor	nplex Trans	ition.
Constituent	Anticipated source form	Mass available to be disturbed (pounds of material)	Total estimated release (pounds)	Limit: Criteria Exemption Threshold (pounds)	Below SQER (Y/N)
Sodium hydroxide	Dried residual solid from process chemical	50	10		Y
Aluminum nitrate nonahydrate	Dried residual solid from process chemical	50	10		Y
Nitric acid	Dried residual solid from process chemical	50	10	4,000 ^{a,b}	Y
Lead	From paint as lead chromate	60	6	10 ^a	Not applicable
Polychlorinated biphenyl	From paint	25	5		Not applicable
Toluene	From paint	85	17	ь	Y
Xylene	From paint	85	17	ъ	Y
Methyl isobutyl ketone	From paint	65	13	ь	Ÿ
Titanium dioxide	From paint	40	8		Not applicable
Iron oxide	From Hanford ash	_	_		Y
Silicon oxide	From Hanford Ash		_		Not applicable
Carbon	From Hanford Ash	-	<5	4,000 ^b	Not applicable
Carbon tetrachloride	From excavation activities	15	15	1,000	Y
Miscellaneous particulate matter		195,000	1,950	2,500°	Not applicable
Nitric acid	From decontamination solution #1	900	180	4,000 ^{a,b,c}	Y
Hydrochloric acid	From decontamination solution #1	200	40	¢	Y
Ammonium fluoride	From decontamination solution #1	200	40	c	Not applicable
Citric acid	From decontamination solution #1	100	20	С	Not applicable
Ethylene glycol monobutyl ether	From decontamination solution #1	550	11	b, c	Not applicable
Triethylamine	From decontamination solution #1	10	2	b, ¢	Y
Isopropanol	From decontamination solution #1	100	20	b, c	Y
Potassium hydroxide	From decontamination solution #1	200	40	С	Y
Cerium nitrate	From decontamination solution #2	6,100	1,220	ď	Not applicable
Lanthanum nitrate	From decontamination solution #2	200	40	d	Not applicable
Neodymium nitrate	From decontamination solution #2	150	30	d	Not applicable

^a WAC 173-400-110(5)(d).

bWAC 173-400-110(5)(d)(e); assume all of carbon converted to VOCs and/or all nitric acid to NO_x.

^o The material safety data sheet (MSDS) for decontamination solution #1 indicates that it is comprised of constituents previously used at PFP in far greater volumes than proposed for this decontamination activity. ^aDecontamination solution #2 has been used previously at PFP and is included for completeness.

^eNot applicable because no ASIL documented.

SQER = small quantity emission rate.

2 3	5.2 DISPERSION MODELING METHODOLOGY
4 5 6 7	Dispersion modeling methodology is not applicable to the PFP Complex transition/security enhancements activities.
8	5.3 AIR QUALITY MODELING RESULTS
9 10 11	Demonstrate compliance with new source review procedures and requirements for toxic air pollutants addressed under WAC 173-460-030, -040, -050, and -060; Model predicted ambient impacts, as required.
12 13 14	Air quality modeling is not applicable to the PFP Complex transition/security enhancements activities.
15	6.0 PROPOSED CONDITIONS AND RESTRICTIONS
16 17 18 19	A summary of proposed approval order conditions and restrictions are provided in Appendix A. Final conditions and restrictions will be provided in the approval order issued by Ecology.
20	7.0 REFERENCES
21 22 23	DOE/EIS-0244-F, Final Environmental Impact Statement Plutonium Finishing Plant Stabilization, U.S. Department of Energy, Washington, D.C.
24 25 26 27 28	DOE/RL-2004-08, New Source Review Notice of Construction Application for Construction or Modification of a Stationary Source; Criteria/Toxic Air Pollutant Emissions Associated with Deactivation of the Plutonium Finishing Plant Complex, Rev. 0, U.S. Department of Energy, Richland, Washington.
29 30 31 32	DOE/RL-2005-13, Action Memorandum for the Plutonium Finishing Plant Above-Grade Structures Non-Time Critical Removal Action, U.S. Department of Energy, Richland Operations Office, Richland, Washington.
33 34 35 36	DOE/RL-2005-14, Removal Action Work Plan for the Plutonium Finishing Plant Above-Grade Structures: Facility Deactivation, U.S. Department of Energy, Richland Operations Office, Richland, Washington.
37 38 39 40 41	Ecology, 2004. Letter, M. Wilson, Ecology, to K. Klein, RL, "04-AMCP-0185, Transmittal of New Source Review Notice of Construction Application for Construction or Modification of a Stationary Source; Criteria/Toxic Air Pollutant Emissions Associated with Deactivation of the Plutonium Finishing Plant Complex," Order No. DE04NWP-001, dated March 30, 2004.
42 43 44 45	Hanford Site Air Operating Permit, 00-05-006, 2001, Washington State Department of Ecology, Washington State Department of Health, U.S. Environmental Protection Agency, Benton Clean Air Authority.

1	Hebdon, J.B., 2002, Letter, 03-RCA-0035, J.B. Hebdon, DOE-RL, to M.A. Wilson, Ecology, Transmittal
2	of Criteria Air Emission New Source Review Evaluation for Plutonium Finishing Plant's (PFP)
3	232-Z Deactivation Activities, dated November 5, 2002.
4	
5	Rasmussen, J.E., 2000, letter, 00-OSS-162, J.E. Rasmussen, DOE-RL, to M.A. Wilson, Ecology, New
6	Source Review for Applicability of Washington Administrative Code (WAC) 173-400 and
7	WAC 173-460: Magnesium Hydroxide Precipitation, dated March 2, 2000.
8	

This page intentionally left blank.




Figure 1. Hanford Site.

060331.1023 F-I




Figure 2. Ventilation Schematic for the 291-Z-1 Stack for the 242-Z and 234-5Z Buildings.




Figure 3. Ventilation Schematic for the 291-Z-1 Stack for the 236-Z Building (PRF).




Figure 4. Ventilation Schematic for the 296-Z-5 Stack.




Figure 5. Ventilation System for the 296-Z-6 Stack.




Figure 6. Ventilation System for the 296-Z-7 Stack (2736-ZB Building).

APPENDIX A

PROPOSED APPROVAL ORDER FOR CRITERIA/TOXIC AIR POLLUTANT EMISSIONS ASSOCIATED WITH TRANSITION OF THE PLUTONIUM FINISHING PLANT COMPLEX

This page intentionally left blank.

APP A-ii

1 APPENDIX A 2 3 4 PROPOSED APPROVAL ORDER FOR 5 CRITERIA/TOXIC AIR POLLUTANT EMISSIONS ASSOCIATED WITH TRANSITION OF THE PLUTONIUM FINISHING PLANT COMPLEX 6 7 8 9 1.0 DETERMINATION 10 11 The Washington State Department of Ecology (Ecology), pursuant to Revised Code of Washington 12 (RCW) 70.94.152, WAC 173-400, and WAC 173-460 makes the following determinations: 13 14 The facility, if operated as herein required, will be in accordance with applicable rules and regulations, as 15 set forth in Chapter 173-400 WAC and 173-460 WAC, and the operation thereof will not result in 16 ambient air quality standards being exceeded. Information submitted in the notice of construction application shows emissions will be below the threshold levels contained in WAC 173-400-110(5)(d), 17 allowing exemption of the proposed activities from New Source Review under WAC 173-400-110. 18 19 20 The proposed project, if constructed and operated as herein required, will provide all known, available, 21 and reasonable methods of emission control. 22 23 24 THEREFORE, IT IS ORDERED that the project as described in said Notice of Construction application 25 (NOCA), and more specifically detailed in plans, specifications, and other information, submitted to the Department of Ecology in reference thereto, is approved for construction, installation and operation, provided 26 27 the following conditions are met: 28 29 30 2.0 CONDITIONS AND RESTRICTIONS 31 32 The following sections provide proposed specific and general approval conditions and restrictions. 33 34 35 2.1 PROPOSED SPECIFIC APPROVAL CONDITIONS 36 37 A. The activities described in the NOCA will be permitted without requiring additional emission 38 controls, provided that the emissions from the stacks, maintain best available control technology 39 (BACT)/ best available control technology for toxics (T-BACT). 40 41 B. For toxic compounds not requiring a T-BACT analysis, the emission limits shall be the Small 42 Quantity Emission Rate (SQER). A modification submittal of a NOCA will be required if the total 43 emissions of toxic air pollutants would exceed the emissions estimated in the NOCA and/or other limits specified under this order. 44 45 46 C. A modification submittal of a NOCA would will be required if total emissions of criteria pollutants exceed the WAC 173-400-110 thresholds. 47 48 49 D. Other, as provided by Ecology. 50

060331.1023 APP A-1

51

2.2 PROPOSED GENERAL APPROVAL CONDITIONS

Applicable records required under this approval will be maintained on file and made available for Ecology inspector requests. Emissions will be compiled into estimates and reported annually beginning as part of the Calendar Year 2006 nonradioactive inventory of airborne emissions, pursuant to WAC 173-400-105.

A. **Fugitive Emissions**: A Fugitive Dust Control Program, consistent with EPA and Ecology guidelines, shall be developed and implemented. A copy of this Program shall be maintained on-site at all times in a place known to facility employees that are responsible for complying with the requirements contained therein and shall be retrievable by those employees at all times when activities regulated by the document are occurring. Program information shall be made available to Ecology upon request.

B. Compliance Assurance Access: Access to the source by EPA or Ecology shall be allowed for the purposes of compliance assurance inspections. Failure to allow access is grounds for revocation of the Order approving the NOC.

C. Modification to Facility or Operating Procedures: Any modification to any equipment or operating procedures, contrary to information in the NOCA, shall be reported to Ecology at least sixty (60) days before such modification. Such modification may require a new, or amended, NOC approval Order.

D. Emissions detrimental to persons or property: No person shall cause or permit the emission of any air contaminant from any source if it is detrimental to the health, safety, or welfare of any person, or causes damage to property or business.

E. Activities Inconsistent with this Order: Any activity undertaken by the Permittee or others, in a manner that is inconsistent with the NOCA, and this determination, shall be subject to Ecology enforcement under applicable regulations.

F. Obligations under Other Laws or Regulations: Nothing in this Order shall be construed to relieve the Permittee of its obligations under any local, state, or federal laws, or regulations.

G. Nothing in this approval shall be construed as obviating compliance with any requirement of law other than those imposed pursuant to the Washington Clean Air Act, and rules and regulations thereunder.

H. Other, as provided by Ecology.

Any violation of such rules and regulations, or of the terms of this approval, shall be subject to the sanctions provided in Chapter 70.94 RCW.

2.2.1 Emission Controls

A. As proposed in the NOCA no additional controls are required as a result of this order of approval. Good operating practices, as described in the NOCA, are in place and can be demonstrated upon inspection. Specific conditions are as follows: TBD

B. Other, as provided by Ecology.

C. Emission control for particle or particle-bound toxic air pollutant (TAP) emissions are high-efficiency particulate air filtration. The use of this system as a required abatement control technology is covered under the radioactive air license, issued by the Washington State Department of Health, with conditions and limitation specified therein. Controls regulated under that approval are deemed sufficient to address concerns over deminimus criteria and/or particulate TAP emissions.

2.2.2 Emission Monitors

No additional monitoring is required for the subject activities.

2,2,3 Manuals

Existing Operations and Maintenance (O&M) manuals for all equipment, procedures, and controls associated with the proposed activities that have the potential to affect emissions to the atmosphere shall be followed. Manufacturers' instructions may be referenced. The O&M manuals shall be updated to reflect any modifications of the process or operating procedures. Copies of the O&M Manuals shall be available to Ecology upon request.

Any required notifications and submittals required under these Approval Conditions shall be sent to:

2.2.4 Notifications and Submittals

Washington State Department of Ecology Nuclear Waste Program 3100 Port of Benton Blvd. Richland, Washington 99354

2.2.5 Recordkeeping

Specific records shall be kept on-site by the Permittee and made available for inspection by Ecology upon request. The records shall be organized in a readily accessible manner and cover a minimum of the most recent sixty (60) month period. The records to be kept shall include the following:

A. Work Package activities and operations data and maintenance and operations records and logs for transition and security enhancements activities that are not addressed as CERCLA actions.

 B. Diesel/gasoline fuel consumption for miscellaneous units will be tracked to verify usage does not exceed the 50,000 gallons per calendar year used to calculate emission estimates. The basis for emission estimates will be maintained on file and available for inspection.

2.2.6 Reporting

Pursuant to Section 2.5 of the NOCA, emissions from miscellaneous sources will be provided to Ecology as part of the diesel engine emission composite in the Hanford Site annual emissions inventory report under WAC 173-400-105. Internal records will be maintained and made available for inspection to verify compliance with the 50,000 gallon diesel fuel use limit for this stationary source.

060331,1023 APP A-3

1						
2	2.3	APPROVAL ORDER AND RESTR	ICTIONS			
3						
4 5	Authorization may be modified, suspended or revoked in whole, or part, for cause including, but not limited to, the following:					
6						
7 8	1.	Violation of any terms or conditions of the	his authorization;			
9 10	2.	Obtaining this authorization by misrepre	sentation, or failure to disclose fully all relevant facts.			
11	Th	e provisions of this authorization are sever	rable and, if any provision of this authorization, or			
12			ation to any circumstance, is held invalid, the application of			
13			e remainder of this authorization, shall not be affected			
14 15		reby.				
16	An	y person feeling aggrieved by this ORDE	R may obtain review thereof by application, within thirty			
17) days of receipt of this ORDER, to:	in the state of approximation, when the state of approximation is a state of approximation.			
18	(),,,,,				
19		Pollution	Control Hearings Board			
20		P.O. Box				
21			Washington 98504-0903			
22		,	50-10-00			
23 24	Co	ncurrently, copies of the application must	be sent to:			
25	Wa	shington State Department of Ecology	Washington State Department of Ecology			
26), Box 47600	3100 Port of Benton Blvd.			
27		ympia, Washington 98504-7600	Richland, Washington 99354			
28	•					
29	Th	ese procedures are consistent with the pro-	visions of Chapter 43.21B RCW, and the rules and			
30		ulations adopted thereunder.				
31	٠					
32						
33 34	DA	ATED at Richland, Washington, this the x	xth day of March 2006.			
35	PR	EPARED AND REVIEWED BY:				
36						
37						
38						
39	Do	ug Hendrickson, P.E.				
40						
41						
42	AP	PROVED BY:				
43						
44						
45						
46	Jar	e Hedges				
47		J				
48						

060331.1023 APP A-4

DISTRIBUTION

MSIN

Jane Hedges, Program Manager Nuclear Waste Program Washington State Department of Ecology P.O. Box 47600 Olympia, Washington 98504-7600

D. W. Hendrickson Washington State Department of Ecology H0-57

O. S. Wang

H0-57

Washington State Department of Ecology

D. Zhen
<u>United States Environmental Protection Agency</u>
Region 10
1200 Sixth Avenue
Seattle, Washington 98101

A. W. Conklin

<u>Washington State Department of Health</u>
7171 Cleanwater Lane, Building 5

Olympia, Washington 98504

C. Kemp

Washington State Department of Health
Division of Radiation Protection
Air Emissions and Defense Waste
309 Bradley Blvd., Suite 201
Richland, WA 99352

Dirk A. Dunning
Oregon Office of Energy
625 Marrian Street N.E., Suite 1
Salem, OR 97301-3742

S. Harris, Director
Confederated Tribes of the Umatilla Indian Reservation
Richland Office of Science and Engineering
750 Swift Boulevard, Suite 12
Richland, Washington 99352

060331.1023 Distr-I

DOE/RL-2004-08, Rev. 1 03/2006

DISTRIBUTION

	ISIN
G. Bohnee	
Nez Perce Tribe	
P. O. Box 365	
Lapwai, Idaho 83540	
R. Jim, Manager	
Environmental Restoration/Waste Management Program Yakama Nation	
P. O. Box 151	
Toppenish, Washington 98948	
Toppenish, Washington 90946	
U.S. Department of Energy, Richland Operations Office	
S. L. Charboneau Ac	6-33
M. F. Jarvis	5-15
W. C. Woolery Ac	6-33
Public Reading Room H2	2-53
Elvan Wanfand	
Fluor Hanford R. W. Bloom	2 10
	3-10 5-50
•	3-30 8-40
(-)	
	3-10
	8-12
	4-35
AOP File HS	8-13
Pacific Northwest National Laboratory	
	8-55

Distr-2

060331,1023